

Chevaline Clearstrip

Purpose & Areas Of Use:

As a safe, gentle-acting but deep penetrating stripper for paint, varnish and polish films on non or semi-porous surfaces. Formulated for easy removal by scrubbing or water jetting.

Product:

A waterborne mildly alkaline clear stripper with mild odour. Contains detergent aids for easy cleaning.

Product Compatibility:

This product will remove most waterbourne coatings, conventional enamels and varnishes, acrylic glaze coats and floor polish systems.

Clearstrip is recommended for use as the cleaner for sacrificial **Clearglaze** anti-graffiti systems and **Clearseal** hard-use areas.

Not recommended for the removal of epoxy, polyurethane and chlorinated rubber coatings. Check for suitability on any surface to be stripped before proceeding with large areas.

Colour:

Water-white

Standard Packs:

4, 15 litre plastic pails.

Physical Properties:

Liquid Material :

Specific Gravity: 1.22

Flash Point: Not applicable - waterborne material.

Application Properties:

Remove all easily removed dirt by sweeping or brushing, and apply **Clearstrip** by brush or roller as a heavy even layer to the surface to be cleaned.

Spreading rate will be 2-4 m²/litre depending on build-up of coating layer to be removed, and surface profile.

Leave **Clearstrip** on the surface for 30-60 minutes, checking periodically to determine softening of the coating layer and depth of penetration. The "peeling" effect occurs quite suddenly after a period of 30+ minutes, even though little seems to have occurred up to that time.

When "peeling" is evident back to original surface, remove the softened amalgam of **Clearstrip** coating by vigorous brushing with a stiff bristle brush, or preferably by water jetting.

Check cleaned surface for any residual patches and reapply **Clearstrip** where necessary.

Finally, hose down the stripped surface and allow to dry before any coating re-application is carried out.

Health And Safety:

Chevaline Clearstrip contains both alkaline and solvent base materials. Wear gloves and goggles when handling **Clearstrip** to prevent skin defatting, and eye-splash respectively. Wear PVC or rubber gumboots when working on floor surfaces. Always relid pails when not in use, and keep away from foodstuffs.

Equus Industries Ltd
PO Box 497
Frankston 3199
Victoria
Phone: 03 9706 6226 Fax 03 9706 4880
Email: tech-support@equus.com.au
Web: www.equus.com.au